



95-PCA-316

Department of Energy

Richland Operations Office P.O. Box 550 Richland, Washington 99352

MAY 25 105

Mr. David L. Lundstrom
Section Manager
200 Areas
Nuclear Waste Program
State of Washington
Department of Ecology
1315 West Fourth Avenue
Kennewick, Washington 99336

Dear Mr. Lundstrom:

HANFORD FACILITY DANGEROUS WASTE PART A PERMIT APPLICATION FORM 3, REVISION 4, FOR THE T PLANT COMPLEX (TSD: T-2-7)

Enclosed is the Hanford Facility Dangerous Waste Part A Permit Application (Part A) Form 3, Revision 4, for the T Plant Complex (T Plant). T Plant is located in the 200 West Area of the Hanford Facility and will be used as a decontamination facility for the Hanford Facility. The Part A, Form 3, has been revised to address the liquid mixed waste storage capacities of the 2706-T railroad sump, 211-T sump, and 221-T Building tank 6-1. These sumps and tank are used for storage of liquid mixed waste generated during decontamination operations at the T Plant Complex. Following a review of the T Plant Complex liquid mixed waste system, it was determined that these units needed to be added to the Part A, Form 3. The maximum storage process design capacity "S02" for the liquid mixed waste storage tanks at T Plant will remain as currently identified (292,990 liters [77,400 gallons]).

The Part A, Form 3, also has been revised to add 32 new dangerous waste numbers for previously unidentified waste with the potential of being stored and/or treated in containers at the T Plant Complex.

These changes to the Part A, Form 3, were made in compliance with Washington Administrative Code 173-303. This regulation requires the submittal of a revised Part A, Form 3, that addresses the treatment, storage, and/or disposal of Dangerous Waste previously unidentified at a treatment, storage, and/or disposal unit.



Mr. David L. Lundstrom 95-PCA-316

-2-

Should you have any questions regarding the T Plant Part A, Form 3, please contact Mr. C. E. Clark of the U.S. Department of Energy, Richland Operations Office on (509) 376-9333 or Mr. R. C. Bowman of the Westinghouse Hanford Company on (509) 376-4876.

Sincerely,

James E. Rasmussen, Director

Environmental Assurance, Permits,

and Policy Division

DOE Richland Operations Office

EAP:CEC

William T. Dixon, Director Environmental Services

Westinghouse Hanford Company

Enclosure:

T Plant Complex Dangerous Waste Part A Permit Application Form 3, Revision 4

cc w/encl:

EDMC, H6-08

- R. Bowman, WHC
- D. Duncan, EPA
- M. Jaraysi, Ecology
- R. Jim, YIN
- D. Powaukee, NPT
- S. Price, WHC
- D. Sherwood, EPA
- J. Wilkinson, CTUIR

cc w/o encl:

W. Dixon, WHC

Please print or type in the unshaded areas only

							i.e., 12	character/inch	<i>).</i>																
F	ORA	1			D.4	BIC	ירחר	NIIC NA/A	CT	. .			u t	Λ.	, n		^	ATION		S ATE I.I					
L	3				- DA	1146	JEKU	OUS WA	21	<u> </u>	'EH	(IVI	111	Ai	<u> </u>	L.I	<u>ر</u>	ATION		7 8 8	<u> </u>	<u> </u>	8	3	6 7
	PPLIC			USE ON	ILY E RECEI	VED	Ţ · · · · · ·																		
H	APP	101 T	/ED	(mo	.,day,&	γr.]											CC	PMMENTS							
	_	\exists																	_						
				REVISED				halou lmark o	a bas	. only	l to i	ndin e		hath.	+b		L	ne first application you are s	b ==i++i==	for very f					
apı	plicat	tior	ı, if	this is y Section	our first	applic	cation an	d you already k	now y	our f	acility	/'s E	PA/S	TATE	. I.D	, N	um	ber, or if this is a revised ap	plication,	enter you	r fac	ility r	EP.	A/ST	ATE
Α.	FIR	sT			•			end provide th		•				•											
		L] 1. —	EXISTI	NG FACI	LITY	(See inst. Complete	ructions for del i item below.)	inition	of "	existii	ng" (facilit	'Y•				2. NEW FAC		•		-			
			ио <u>.</u>) 1	DAY		7 C	PERATIC	TING FACILITIE ON BEGAN OR T oxes to the left	THE D	ATE (THE	DA'	TE (n CTIO	no., o N CC	laγ. Miv	&) IEN	/r.) CED	MO. DAY		FOR NEW PROVIDE (mo., day, TION BEG, EXPECTED	THE & v	DATE V/ OF OR IS	E. PÉRA	۸-	
8.	RE	_	_		•			low and comple		ction	l abo	ve/								W	·				
		_						TATUS PERMIT										2. FACILITY	HAS A F	INAL PER	MIT				
	PRC	CE	SS (ODE - E	nter the	code	ACITIES from the	list of process	code	s belo	w th	at be	st d	escrib	es (e a c	h po	rocess to be used at the fac	ility. Ter	lines are	prov	rided	for c	enter	ing
	prod	86. :08	11 to 6 <i>(in</i> :	nore line <i>cluding i</i>	s are ne Is design	eded, n cap	enter the ecity) in t	e code(s) in the the space provi	ded or	prov	ided. (Sect	ion l	II-C).	Cess	will	be	use	d that is not included in the	list of co	des below	, th	en de	scril	be th	16
В.	PRO	CE	SS [ESIGN (CAPACI	TY - F	or each o	ode entered in	colum	ın A e	enter	the s	сара	city o	f th	e pi	roce	ess.							
				T - Enter																					
	2. U	nly	the	MEASU units of	RE - For measur	each e that	amount are liste	entered in colu d below should	mn B(l), en ied.	iter th	ne co	de fi	rom t	he li	st c	of u	nit measure codes below th	at describ	es the un	it of	meas	sure	use	1.
							PRO- CESS	APPROPRIA MEASURE F											PRO- CESS	APPR	OPR	IATE	UNI	TS O	F
				PROCES	S.		CODE	DESIGN	CAPA	CITY						_		PROCESS	CODE	DĚ	SIGN	CAF	AC	ITY	
	Stor	-		R (barrel	daım i	etci	S01	GALLONS OR	LITER	ıs.							eat ANK	ment:	T01	GALLON	10 0	בם ה	. V 1	n P	
	TAN	iΚ	E PIL		, 4,011,	,	S02 S03	GALLONS OR CUBIC YARDS	LITER OR	S								ACE IMPOUNDMENT	T02	LITERS	PER	DAY			
	SUF	FA	CE I	MPOUN	DMENT		S04	CUBIC METER GALLONS OR		s						IN	CIN	ERATOR	Т03	LITERS TONS P	PER FR H	DAY	OR		
	Disp																			METRIC GALLON LITERS	IS P	ER H	OUR	OR	:
	LAN			WELL			D80 D81	GALLONS OR ACRE-FEET (to would cover o	he vol	umo t						0.	THE	R (Use for physical, chemic all or biological treatment	al, T04	GALLON	IS P	ER DA		OR	
								depth of one i	oot)		a					pr	oce	eses not occurring in tanks, ce impoundments or inciner		LITERS	PER	UAY			
				ICATION POSAL	1		D82 D83	ACRES OR HE	DAY							aţ	ors.	Describe the processes in pace provided; Section III-C.							
	SUR	FA	CE I	MPOUNI	DMENT		D84	GALLONS OR	LITER	s															
	LIMIC	т с	E 841	EASURE		,	UNIT OF MEASURI CODE	Ē		JNIT (DE 140	EACI	IDE				ME.	IIT OF ASURE ODE UN	T 05 U5	4.01105			ME	NIT (IRE
	GAL	LO	NS.					 3	ī	ITERS	S PER	DA'	Y					V AC	RE-FEET	ASURE				CODE	
	CUB	IC	YAR	DS				L C	7	ONS JETRI	PER I	HOU NS F	R PER⊦	łour				D HE	RES	ETER	• • •				. F . B
	GAL	LO	NS I						L	ITERS	PER	HO	UR.					Н							Q.
_				hold 2	UU gallo	ns an	a the oth	er can hold 40	o gallo	ns.	The f	nber. acilit	y als	o has	X-2 an	inc	ine	vi: A facility has two storage rator that can burn up to 20	e tanks, gallons p	one tank o er hour.	Bn				
1 1	111 4	. P	RO-		B. I	PROCI	ESS DESI	GN CAPACITY	12	UNIT		FOR			A,	PR ESS	io-	B. PROCESS D	ESIGN CA	APACITY			_	FC	OR.
I I N I	M (6	00 0m)E list				MOUNT		OF	MEA- JRE		FICI USE ONLY	,	I M N B	1110	OD	Ε	1. AMOU			OF	UNIT MEA JURE	[]	OFFI US	CIAL SE
E	E #	DO	ve)			102				nter de)		J14E 1		E E	at	10 V	e)	(specify,			1 10	enter ode)		ON	LY
<i>X</i> -:	1 5	o	2			• • •	600		1	G		Τ		5	T	0	4	3,785				v		Ţ	
X	2 7	0	3				20	٠		E	$\dagger \dagger$	+		6	\vdash	0	5	35,170		<u> </u>	\vdash	c	十	+-	
1	s	0	2		2	92,	990		1-1	L		+	\dagger	7								+	+	+	-
2	T	0	1	-		52,	996			V		\dagger		8	H							_	+	-	\vdash
3	T	0	4				1.8		† †	W	$\dagger \dagger$	\dagger		9	H	-				· · · · · · · · · · · · · · · · · · ·	\vdash	+	+		-
4	s	0	1		7	57,	082			_ 		+	1-	10		_						+	+	1-1	-

Continued from the front,

111	PROCESSES	(continued)

C. SPACE FOR ADDITIONAL PROCESS CODES OR FOR DESCRIBING OTHER PROCESS (code "TO4"). FOR EACH PROCESS ENTERED HERE INCLUDE DESIGN CAPACITY.

REFER TO FOLLOWING PAGES

IV. DESCRIPTION OF DANGEROUS WASTES

- A. DANGEROUS WASTE NUMBER Enter the four digit number from Chapter 173-303 WAC for each listed dangerous waste you will handle. If you handle dangerous wastes which are not listed in Chapter 173-303 WAC, enter the four digit number(s) that describes the characteristics and/or the toxic contaminants of those dangerous wastes.
- B. ESTIMATED ANNUAL QUANTITY For each listed waste entered in column A estimate the quantity of that waste that will be handled on an annual basis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non-listed waste(s) that will be handled which possess that characteristic or contaminant.
- C. UNIT OF MEASURE For each quantity entered in column 8 enter the unit of measure code. Units of measure which must be used and the appropriate codes are:

ENGLISH UNIT OF MEASURE	CODE	METRIC UNIT OF MEASURE	CODE
POUNDS		KILOGRAMS	

If facility records use any other unit of measure for quantity, the units of measure must be converted into one of the required units of measure taking into account the appropriate density or specific gravity of the waste.

D. PROCESSES

1. PROCESS CODES:

For listed dangerous waste: For each listed dangerous waste entered in column A select the code(s) from the list of process codes contained in Section III to indicate how the waste will be stored, treated, and/or disposed of at the facility.

For non-listed dangerous westes: For each characteristic or toxic contained in Column A, select the code(s) from the list of process codes contained in Section III to indicate all the processes that will be used to store, treat, and/or dispose of all the non-listed dangerous wastes that possess that characteristic or toxic containing.

Note: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three as described above; (2) Enter "000" in the extreme right box of Item IV-D(1); and (3) Enter in the space provided on page 4, the line number and the additional code(s).

2. PROCESS DESCRIPTION: If a code is not listed for a process that will be used, describe the process in the space provided on the form.

NOTE: DANGEROUS WASTES DESCRIBED BY MORE THAN ONE DANGEROUS WASTE NUMBER - Dangerous wastes that can be described by more than one Waste Number shall be described on the form as follows:

- 1. Select one of the Dangerous Waste Numbers and enter it in column A. On the same line complete columns 8, C, and D by estimating the total annual quantity of the waste and describing all the processes to be used to treat, store, and/or dispose of the waste.
- 2. In column A of the next line enter the other Dangerous Waste Number that can be used to describe the waste. In column D(2) on that line enter "included with above" and make no other entries on that line.
- 3. Repeat step 2 for each other Dangerous Waste Number that can be used to describe the dangerous waste.

EXAMPLE FOR COMPLETING SECTION IV (shown in line numbers X-1, X-2, X-3, and X-4 below) - A facility will treat and dispose of an estimated 900 pounds per year of chrome shavings from leather tenning and finishing operation. In addition, the facility will treat and dispose of three non-listed wastes. Two wastes are corrosive only and there will be an estimated 200 pounds per year of each waste. The other waste is corrosive and ignitable and there will be an estimated 100 pounds per year of that waste. Treatment will be in an incinerator and disposal will be in a landfill.

											D. PROCESSES									
	DANGEROUS WASTE NO.			ю.		B. ESTIMATED ANNUAL QUANTITY OF WASTE		C. UNI OF MEA SURE (anter code)			1.	PRO	OCE (en		COL	DES			2. PROCESS DESCRIPTION (if a code is not entered in D(1))	
X-1	K	T	0	5	4		300		P		$r \circ 3$	D	8	0		T				
X-2	0	1	0	0	2		400	Γ	P		т о з	D	8	0		T - T		7	7	
X-3	0	, 7	0	0	1	Γ	100		P		T 0 3	D	U	0				-		
X-4	D	1	0	0	2						T 0 3	D	8	0		77			1	included with above

III. C., PROCESSES

The T Plant Complex (T Plant) is located in the 200 West Area of the Hanford Facility and consists of two main structures, the 221-T Building (221-T) and the 2706-T Building (2706-T), and various support structures and storage units within T Plant. The 221-T and 2706-T buildings are used for the storage (tank, container, and miscellaneous equipment) and treatment (tank, container, and decontamination activities) of mixed and/or dangerous waste before transfer to the Double-Shell Tank (DST) System, the Central Waste Complex (CWC), and/or the 616 Nonradioactive Dangerous Waste Storage Facility (616 NRDWSF). The various support structures and storage units are used for storage, sampling, and treatment of mixed and/or dangerous waste until processed and transferred to the CWC and/or the 616 NRDWSF. The T Plant boundary is defined by the chain link fence enclosing the complex.

The following are the storage and treatment processes for T Plant.

<u>S02</u>

Liquid mixed waste from decontamination and treatment activities within T Plant enters the T Plant tank system and is stored until transferred to the DST System.

The liquid mixed waste from 2706-T decontamination activities is currently stored in the railroad pit sump [23,000 liters (6,100 gallons)] located in the 2706-T. The liquid mixed waste is transferred by underground transfer piping from 2706-T to the 211-T sump [15,000 liters (3,900 gallons)], located on the east side of the 2706-T, then transferred to the 221-T tank system. The liquid mixed waste is automatically pumped to the 221-T tank system when the waste reaches a designated level. The maximum tank storage design capacity that is maintained for the railroad pit sump and 211-T sump is 38,000 liters (10,000 gallons).

Liquid mixed waste from 2706-T and 221-T decontamination and treatment activities is currently stored in the 221-T tank system. The 221-T tank system currently consists of six stainless steel storage tanks: tank 5-6 [17,400 liters (4,600 gallons) design capacity], tank 5-7 [38,000 liters (10,000 gallons) design capacity], tank 5-9 [18,200 liters (4,800 gallons) design capacity], tank 6-1 [76,000 liters (20,000 gallons) design capacity], tank 11-R [53,000 liters (14,000 gallons) design capacity], and tank 15-1 [53,000 liters (14,000 gallons) design capacity]. The tanks are located in reinforced concrete cells within 221-T. The maximum tank storage design capacity of the six storage tanks is 255,600 liters (67,400 gallons). Liquid mixed waste is transferred to the DST System from the 221-T tanks.

In a future process, the liquid mixed waste from 2706-T decontamination activities will be transferred and stored in proposed tanks located outside of 2706-T. The addition of these proposed storage tanks will eliminate the need for storage in the railroad pit and 211-T sumps. With the addition of the proposed storage tanks, liquid mixed waste would no longer be transferred to the 221-T tank system but will be transported by railcar to the DST System. It is anticipated that the new tanks will have a total design capacity of 114,000 liters (30,000 gallons).

III. C., PROCESSES (Continued)

The maximum volume of liquid mixed waste (Process Design Capacity) that will be stored at T Plant at any time is 292,990 liters (77,400 gallons). The T Plant tank systems will be managed in a manner that ensures the Process Design Capacity is not exceeded.

T01

Liquid mixed waste that is stored in tank 15-1 in 221-T is normally transferred by railroad car to the DST system. If the liquid mixed waste is transferred by underground pipelines, tank 15-1 may be used to treat the waste to a pH greater than 12.5 and nitrite concentration greater than 600 ppm before transfer to the DST system. This treatment process makes the liquid mixed waste more amenable to storage in the DST system. The maximum tank treatment process design capacity for tank 15-1 is 52,996 liters (14,000 gallons) per day.

T04

Decontamination and treatment activities occur in the 221-T canyon, 2706-T bay, and in other support facilities and units located within T Plant. Decontamination and treatment methods may incorporate a variety of technologies to remove contamination. The technologies include, but are not limited to; immersion treatment; spray batch treatment; and steam, water, ice, carbon dioxide, chemical, or abrasive blasting. Some equipment, discarded materials, or solid wastes generated by the treatment processes may be treated by immobilization or encapsulation of the dangerous constituents. Items may be recycled or properly disposed on the Hanford Facility after leaving T Plant.

The 2706-T is used to decontaminate various types of equipment (e.g., tools, railroad equipment, buses, trucks, automobiles, cranes, earth moving equipment, and other large and small pieces of plant process equipment) by using steam, water, chemicals, abrasive blasting (e.g., ice, carbon dioxide) and/or other methods to remove the contamination. The decontamination and treatment activities in 2706-T occur over railroad and automotive pits located within the building. The railroad pit is 16.9 meters (55 feet)long by 5.2 meters (17 feet) wide by 1.8 meters (6 feet) deep. The automotive pit is 9.1 meters (30 feet) long by 1.2 meters (4 feet) wide by 1.8 meters (6 feet) deep. The liquid waste generated by this process is currently collected in the railroad pit sump, transferred to the 211-T sump, and then transferred to the 221-T tank system.

Decontamination and treatment activities occur in 221-T in stainless steel immersion tanks (e.g., thimbles and troughs), immersion or spray batch treatment systems, enclosed abrasive blasting modules, designated areas on the canyon deck, or designated areas within the railroad tunnel. The activities consist of decontaminating and treating process equipment (i.e., pipelines, jumpers), other pieces of equipment (e.g., pumps, motors, damaged tools), and discarded materials. The process consists of placing the contaminated items in the immersion tanks, batch containment systems, treatment modules, or designated areas on the canyon deck and using steam, water, chemicals, abrasive blasting (e.g., ice, carbon dioxide) and/or other methods to remove

III. C., PROCESSES (Continued)

contamination. Liquid mixed waste generated by this process is transferred to the 221-T tank system and then to the DST system. Some equipment, discarded materials, or solid waste may be immobilized or encapsulated before leaving T Plant.

The maximum decontamination and treatment process design capacity within T Plant is 1.8 metric tons (2 tons) per hour.

S01, T04

Storage and treatment of dry and liquid mixed and dangerous waste in various sized containers including railroad cars may take place in the 221-T canyon, 221-T railroad tunnel, 2706-T bay, and in other support structures and storage units located within the boundaries of T Plant. Container storage and treatment capability at T Plant is required to: (1) complete laboratory analysis and characterization of mixed and/or dangerous waste samples before transferring the waste containers to the CWC, 616 NRDWSF, or the DST System; or (2) absorb, neutralize, immobilize, encapsulate, or otherwise stabilize the contents of some containers before transfer.

The maximum container storage process design capacity is 757,082 liters (200,000 gallons); and the maximum container treatment process design capacity is 3,785 liters (1,000 gallons) per day.

S05

The designation SO5 (storage miscellaneous) indicates that solid mixed waste is stored on the canyon deck, in 221-T railroad tunnel, in various cells in the 221-T, and in 2706-T. This waste is considered to be stored in a containment building subject to the requirements of 40 CFR 265, Subpart DD rather than a waste pile subject to the requirements of 40 CFR 265, Subpart L. The solid mixed waste consists of process equipment, jumpers, and various other items awaiting decontamination, treatment, or repackaging prior to final disposition.

The maximum storage miscellaneous process design capacity in 221-T and 2706-T is 35,170 cubic meters (46,000 cubic yards).

Continued from page 2. NOTE: Photocopy this page before completing if you have more than 26 wastes to list. I.D. NUMBER (entered from page 1) W A 7 8 9 0 0 0 8 9 6 7 IV. DESCRIPTION OF DANGEROUS WASTES (continued) D. PROCESSES C. UNIT OF MEA-SURE (enter code) A. N DANGEROUS O WASTE NO. B. ESTIMATED ANNUAL QUANTITY OF WASTE 1. PROCESS CODES (enter) 2. PROCESS DESCRIPTION (if a code is not entered in D(1)) (enter code) loiol **SO2** Ť0 Ì Ť04 Storage-Tank/Treatment-Tank-Other 126,552,271 0002 D (Decontamination Activities) 3 0 0 3 D D 0 0 4 TI 5 D 0 0 6 D 0 0 6 D 0 0 8 D lolo 8 0 0 0 9 T 10 D 0 0 1 T^{T} 11 0 D 1 1 D 0 1 8 13 D 0 1 9 D 0 2 15 D |0|2|8 1 - 6 D 0 2 9 \top 17 0 3 0 D 0 3 D 3 19 D 0 3 4 T 20 0 3 5 D 03 6 D 22 0 D 3 8 23 D 0 3 9 T 0 4 D 0 25 0 4 lD. 1

Continued from page 2. NOTE: Photocopy this page before completing if you have more than 26 wastes to list. I.D. NUMBER (entered from page 1) W A 7 8 9 0 0 0 8 9 6 7 IV. DESCRIPTION OF DANGEROUS WASTES (continued) D. PROCESSES C. UNIT OF MEA-SURE (enter N DANGEROUS O WASTE NO. B. ESTIMATED ANNUAL QUANTITY OF WASTE 1. PROCESS CODES 2. PROCESS DESCRIPTION (if a code is not entered in D(1)) (enter) (enter code) Storage-Tank/Treatment-Tank-Other T 0 1 K \$02 TOI T04 |T|0|2 (Decontamination Activities)(Cont.) W 3 C 2 0 P 0 1 Р 0 \neg 0 0 1 \top F ٥ 0 2 0 0 3 \mathbf{I} F 0 0 4 loloi 5 ামা 11 9 0 3 Included With Above 01 0 S01 lD 1 907,185 T04 Storage-Container/Treatment-Other 13 2 ۵۱ 0 0 0 0 0 3 D \top D 0 0 16 DOOD5 17 D 0 0 6 7 18 מו 0 ol D olola TI 20 D 0 0 9 21 0 1 0 22 ס מ I 1 001 2 T 1 3 D 0 25 0 1 4 D 26

Continued from page 2. NOTE: Photocopy this page before completing if you have more than 26 wastes to list. 1.D. NUMBER (entered from page 1) W A 7 B 9 0 0 0 B 9 6 7 IV. DESCRIPTION OF DANGEROUS WASTES (continued) D. PROCESSES C. UNIT OF MEA-SURE lenter L N DANGEROUS N O WASTE NO. B. ESTIMATED ANNUAL QUANTITY OF WASTE 2. PROCESS DESCRIPTION (if a code is not entered in D(1)) 1. PROCESS CODES (enter) (enter code) 1 Š01 Ť04 Storage-Container/Treatment-Other D 0 6 D 0 1 7 (Continued) 3 D 0 1 8 1 9 0 TT ŢŢ D 0 2 0 0 2 D T "T D 0 2 2 D 0 3 Ш 7-7 D 0 2 4 10 2 5 D 0 11 D 0 2 6 12 2 0 13 lD. 0 2 8 14 D 0 2 9 D 0 3 0 16 D 0 3 1 17 2 D 0 3 $\Pi\Pi$ \top 18 3 3 D 0 D 3 0 20 D 0 3 5 D 0 3 22 D 0 3 7 23 ם 0: 3 8 11 T 24 D 0 3 9 Т-Т \sqcap 25 D 0 4 0

Continued from page 2.

NOTE: Photocopy this page before completing if you have more than 26 wastes to list. 1.D. NUMBER (entered from page 1) W A 7 8 9 0 0 0 8 9 6 7 IV. DESCRIPTION OF DANGEROUS WASTES (continued) D. PROCESSES C. UNIT OF MEA-SURE (enter A. N DANGEROUS O WASTE NO. B. ESTIMATED ANNUAL QUANTITY OF WASTE 2. PROCESS DESCRIPTION (if a code is not entered in D(1)) 1. PROCESS CODES (enter) (enter code) †0<u>4</u> 1 \$01 0 4 Storage-Container/Treatment-Other D 2 D 0 4 3 (Continued) 3 W T 0 1 W T 0 2 Б W C 2 0 1 6 Р 0 W 1 7 WP 0 2 WP 0 Т W 0 0 10 F 0 0 11 F 0 0 2 F 12 0 0 3 F 13 0 0 4 14 F 0 0 5 F 2 0 0 1 1 16 F 0 2 17 F lö 2 2 TT 18 F 0 2 3 19 F 0 2 6 20 0 2 7 21 0 2 8 22 F 0 3 9 $\mathsf{T}\mathsf{T}\mathsf{T}$ 23 Ulo 0 1 TT TT 24 Ulo 0 2 П 25 U 0 0 3 26

Continued from page 2. NOTE: Photocopy this page before completing if you have more than 26 wastes to list. I.D. NUMBER (entered from page 1) W A 7 8 9 0 0 0 B 9 6 7 IV. DESCRIPTION OF DANGEROUS WASTES (continued) D. PROCESSES L N DANGEROUS WASTE NO. C. UNIT OF MEA-SURE (enter B. ESTIMATED ANNUAL QUANTITY OF WASTE 1. PROCESS CODES (enter) 2. PROCESS DESCRIPTION (if a code is not entered in D(1)) (enter code) Storage-Container/Treatment-Other ŤO4 ulolo ulolo (Continued) U U U U \Box U U ПΙ U U U (0) lU U $\mathsf{T}\mathsf{T}\mathsf{T}$ U iU. U 0 2 U 0 2 T 2 8

T Plant Complex **4, 05/25/95**, Page 11 of 40

Continued from page 2.

NOTE: Photocopy this page before completing if you have more than 26 wastes to list. I.D. NUMBER (entered from page 1) W A 7 B 9 0 0 0 8 9 6 7 IV. DESCRIPTION OF DANGEROUS WASTES (continued) D. PROCESSES C. UNIT OF MEA-SURE A. N DANGEROUS O WASTE NO. コスト B. ESTIMATED ANNUAL QUANTITY OF WASTE 1. PROCESS CODES (enter) 2. PROCESS DESCRIPTION (if a code is not entered in D(1)) (anter code) codel K ŚOÌ Storage-Container/Treatment-Other Ť04 lo' 3 3 (Continued) TIT U T lo 3 9 U la. lu ľU lu lo lu lo U lo. l٥

Continued from page 2. NOTE: Photocopy this page before completing if you have more than 26 wastes to list. I.D. NUMBER (entered from page 1) W A 7 8 9 0 0 0 8 9 6 7 IV. DESCRIPTION OF DANGEROUS WASTES (continued) D. PROCESSES C. UNIT OF MEA-SURE N DANGEROUS O WASTE NO. B. ESTIMATED ANNUAL QUANTITY OF WASTE 1. PROCESS CODES (enter) 2. PROCESS DESCRIPTION (if a code is not entered in D(1)) lenter (enter code) code) 0 0 6 0 K SO1 Storage-Container/Treatment-Other 2 U 0 6 (Continued) U 0 6 τ 6 3 0 5 0 6 \Box 6 U 0 6 l 6 7 lu lo l 6 l 7 8 U 0 6 8 | 0 0 6 9 10 0 7 0 U 11 07 U 2 l٥ TT13 ulol7 3 0 7 4 15 |U|0|7|5 16 0 6 7 17 7 0 18 7 0 8 TT 0 9 0 | 8 | 0 21 0 8 1 lo | 8 | \top 23 0 8 3 24 0 8 4 25 8 5 0 26 8

Continued from page 2, NOTE: Photocopy this page before completing if you have more than 26 wastes to list. I.D. NUMBER (entered from page 1) W A 7 8 9 0 0 0 8 9 6 7 IV. DESCRIPTION OF DANGEROUS WASTES (continued) D. PROCESSES C. UNIT OF MEA-SURE N DANGEROUS O WASTE NO. B. ESTIMATED ANNUAL QUANTITY OF WASTE 1. PROCESS CODES (enter) 2. PROCESS DESCRIPTION (if a code is not entered in D(1)) (enter (enter code) ulolal T04 Storage-Container/Treatment-Other u lo l 8 | 8 (Continued) TIT U|0|9 Tl0 | 9: TÓ 0 3 auT $\mathsf{T}\mathsf{T}$

Continued from page 2. NOTE: Photocopy this page before completing if you have more than 26 wastes to list. I.D. NUMBER (entered from page 1) W A 7 8 9 0 0 0 B 9 6 7 IV. DESCRIPTION OF DANGEROUS WASTES (continued) D. PROCESSES C. UNIT OF MEA-SURE (enter N DANGEROUS O WASTE NO. B. ESTIMATED ANNUAL QUANTITY OF WASTE 1. PROCESS CODES 2. PROCESS DESCRIPTION (if a code is not entered in D(1)) (enter) (enter code) code) \$0i T04 Storage-Container/Treatment-Other 1 1 (Continued) U T \top $\mathsf{T}^{\dagger}\mathsf{T}$ 2 8 Π ΤΤ $\mathsf{T}\mathsf{T}$

T Plant Complex 4, 05/95/95, Page 15 of 40

Continued from page 2, NOTE: Photocopy this page before completing if you have more than 26 wastes to list. 1.D. NUMBER (entered from page 1) W A 7 B 9 0 0 0 B 9 6 7 IV. DESCRIPTION OF DANGEROUS WASTES (continued) D. PROCESSES C. UNIT OF MEA-SURE (enter code) A. N DANGEROUS O WASTE NO. B. ESTIMATED ANNUAL QUANTITY OF WASTE 1. PROCESS CODES (enter) 2. PROCESS DESCRIPTION (if a code is not entered in D(1)) $1 \Box$ Š0 İ Ť0À Storage-Container/Treatment-Other (Continued) 7-1 \Box U U IJ TT \top \Box $\mathsf{T}\mathsf{T}\mathsf{T}$ U ТТ TT \top 6 3 TI

u

1 1

1 1

Continued from page 2. NOTE: Photocopy this page before completing if you have more than 26 wastes to list. I.D. NUMBER (entered from page 1) WA7890008967 IV. DESCRIPTION OF DANGEROUS WASTES (continued) D. PROCESSES C. UNIT OF MEA-SURE (enter A. N DANGEROUS O WASTE NO. 8. ESTIMATED ANNUAL QUANTITY OF WASTE 2. PROCESS DESCRIPTION (if a code is not entered in D(1)) 1. PROCESS CODES (enter code) ŚOÌ **T04** Storage-Container/Treatment-Other ТП 1 6 8 (Continued) Į $\mathsf{T}\mathsf{T}$ $\mathsf{T}\mathsf{T}\mathsf{T}$ $\mathsf{T}\mathsf{T}$ $\mathsf{T}\mathsf{T}$ 8 2 8 4 $\mathsf{T}\mathsf{T}$ 8 8 9 0

Continued from page 2. NOTE: Photocopy this page before completing if you have more than 26 wastes to list. 1.D. NUMBER (entered from page 1) A 7 8 9 0 0 0 8 9 6 7 IV. DESCRIPTION OF DANGEROUS WASTES (continued) D. PROCESSES C. UNIT OF MEA-SURE lenter A. DANGEROUS WASTE NO. B. ESTIMATED ANNUAL QUANTITY OF WASTE 2. PROCESS DESCRIPTION (if a code is not entered in D(1)) 1. PROCESS CODES (enter) (enter code) K T04 Storage-Container/Treatment-Other ŚOÌ (Continued) U U I I U 2 U U $\Box \Box$ U U U U U U U U U Ţ U U U

Continued from page 2. NOTE: Photocopy this page before completing if you have more than 26 wastes to list. I.D. NUMBER (entered from page 1) W A 7 8 9 0 0 0 8 9 6 7 IV. DESCRIPTION OF DANGEROUS WASTES (continued) D. PROCESSES C. UNIT OF MEA-SURE N DANGEROUS O WASTE NO. レーアロ B. ESTIMATED ANNUAL QUANTITY OF WASTE 1. PROCESS CODES (enter) 2. PROCESS DESCRIPTION (if a code is not entered in D(1)) (enter (enter code) K \$01 Ť04 Storage-Container/Treatment-Other (Continued) U lu U U U U U | 3 U U | 3 Р

Continued from page 2. NOTE: Photocopy this page before completing if you have more than 26 wastes to list. I.D. NUMBER (entered from page 1) W A 7 8 9 0 0 0 B 9 6 7 IV. DESCRIPTION OF DANGEROUS WASTES (continued) D. PROCESSES C. UNIT OF MEA-SURE (enter N DANGEROUS O WASTE NO. B. ESTIMATED ANNUAL QUANTITY OF WASTE 2. PROCESS DESCRIPTION (if a code is not entered in D(1)) 1. PROCESS CODES (enter) lenter codes code) Plolol Storage-Container/Treatment-Other Š0. T04 P (Continued) P Įр lР Р P P Р P TTTp P Γ P P P P P P р TP p р p Р Þ

Continued from page 2. NOTE: Photocopy this page before completing if you have more than 26 wastes to list. I.D. NUMBER (entered from page 1) WA7890008967 IV. DESCRIPTION OF DANGEROUS WASTES (continued) D. PROCESSES C. UNIT OF MEA-SURE A. N DANGEROUS O WASTE NO. LINE B. ESTIMATED ANNUAL QUANTITY OF WASTE 1. PROCESS CODES (enter) 2. PROCESS DESCRIPTION (if a code is not entered in D(1)) lenter (enter code) code) K PO T04 Storage-Container/Treatment-Other 3 4 Р (Continued) Р ĮР P Р Р P lp. TT Įр lр р P 4 8 Р þ Р ĮР P P Р Р ECL30 - 271 -ECY 030-31 Form 3

Continued from page 2. NOTE: Photocopy this page before completing if you have more than 26 wastes to list. I.D. NUMBER (entered from page 1) W A 7 8 9 0 0 0 8 9 6 7 IV. DESCRIPTION OF DANGEROUS WASTES (continued) D. PROCESSES C. UNIT OF MEA-SURE (enter A. N DANGEROUS O WASTE NO. B. ESTIMATED ANNUAL QUANTITY OF WASTE 1. PROCESS CODES 2. PROCESS DESCRIPTION (if a code is not entered in D(1)) (enter code) 1 6 Š0 i **T04** Storage-Container/Treatment-Other Р lol 4 (Continued) 2 p 0 6 5 3 P 0 6 6 6 P 0 T-1 5 P 0 6 8 Р 0 6 9 7 017 P 0 Р 0 7 1 9 lр 0 7 2 $\mathsf{T}^{\dagger}\mathsf{T}$ 10 ١p 0 7 3 TTT7 P 0 4 12 р 0 7 P 0 7 6 P 0 7 7 15 P 0 7 8 16 P 0 8 1 17 lo | 8 | 2 P 18 ĺР 0 8 4 19 0 8 5 P 20 Р 0 8 21 0 8 р 8 Т 22 lР 0 8 9 23 ļр 9 0 2 24 0 9 3 25 ŀР 0 9 4 26

Continued from page 2. NOTE: Photocopy this page before completing if you have more than 26 wastes to list. I.D. NUMBER (entered from page 1) W A 7 8 9 0 0 0 8 9 6 7 IV. DESCRIPTION OF DANGEROUS WASTES (continued) D. PROCESSES N DANGEROUS N O WASTE NO. C. UNIT OF MEA-SURE (enter B. ESTIMATED ANNUAL QUANTITY OF WASTE 1. PROCESS CODES 2. PROCESS DESCRIPTION (if a code is not entered in D(1)) (enter) (enter code) code) <u>P|0|9|6</u> Š01 Ť04 Storage-Container/Treatment-Other T.TP 0 9 7 (Continued) P Р P P P P тП p Р P .7 P p P P P lΡ p P TT lР P P р T P P Included With Above

Continued from page 2. NOTE: Photocopy this page before completing if you have more than 26 wastes to list. I.D. NUMBER (entered from page 1) W A 7 8 9 0 0 0 8 9 6 7 IV. DESCRIPTION OF DANGEROUS WASTES (continued) D. PROCESSES C. UNIT OF MEA-SURE *lenter* N DANGEROUS O WASTE NO. B. ESTIMATED ANNUAL QUANTITY OF WASTE 2. PROCESS DESCRIPTION (if a code is not entered in D(1)) 1. PROCESS CODES (enter) (enter code) code) ס וס ו 4,536 \$05 Storage-Miscellaneous 2 (Containment Building) D | O | O | 2 3 0 D 0 3 D 0 0 4 5 D 0 0 5 6 D 0 0 6 7 00 D lD. 1010 8 מו 0 0 9 10 al 0 1 0 11 D 0 1 1 D 0 8 1 13 9 D 0 1 D 0 2 2 15 D 0 2 8 מו 0 2 9 17 D 0 3 0 18 3 3 D 0 19 3 D Ó 4 20 0 3 5 D 21 D 0 3 6 D 0 3 22 8 23 D 0 3 9 'םו 0 4 0 25 0 D 4 26

Continued from page 2. NOTE: Photocopy this page before completing if you have more than 26 wastes to list. I.D. NUMBER (entered from page 1) W A 7 B 9 0 0 0 B 9 6 7 IV. DESCRIPTION OF DANGEROUS WASTES (continued) D. PROCESSES C. UNIT OF MEA-SURE N DANGEROUS O WASTE NO. B. ESTIMATED ANNUAL QUANTITY OF WASTE 1. PROCESS CODES (enter) 2. PROCESS DESCRIPTION (if a code is not entered in D(1)) (enter (enter code) WIT K 0 Storage-Miscellaneous 2 WIT 0 2 (Containment Building) (Continued) 3 W/C 0 2 P 0 W 1 \top P 0 2 F 0 0 1. FO 0 FIO 0 3 F l٥ 0 4 10 F 5 0 0 F 0 3 9 Included With Above 12 au13 14 15 16 17 18 19 20 \top 21 22 23 24 25 26

Continued from the front.

IV. DESCRIPTION OF DANGEROUS WASTES (continued)

E. USE THIS SPACE TO LIST ADDITIONAL PROCESS CODES FROM SECTION D(1) ON PAGE 3.

The T Plant Complex (T Plant) is used for the storage and treatment of mixed waste and/or dangerous waste. The mixed waste is transferred to the Double-Shell Tank System and/or Central Waste Complex. The dangerous waste is transferred to the 616 Nonradioactive Dangerous Waste Storage Facility.

The dangerous waste numbers identified in Section IV.A. are associated with mixed and/or dangerous waste that could be stored and/or treated at T Plant. The mixed and/or dangerous waste consists of listed waste, characteristic waste, waste from nonspecific sources, toxicity characteristic waste, and state-only waste (extremely hazardous and dangerous waste). Multi-source leachate (FO39) is included as a waste derived from nonspecific source wastes FOO1 through FOO5.

The estimated annual quantities of mixed waste listed for SO1, SO2, SO5, TO1, and TO4 and dangerous waste for SO1 and TO4 represent the maximum quantities of dry and liquid waste that could be stored and treated at T Plant. Future operations might necessitate an increase in excess of these estimates and a revision could be pursued as required by the dangerous waste regulations.

V. FACILITY DRAWING Refer to attached d	rawing.		
All existing facilities must include in the space provided on p	ge 5 a scale drawing of the facility (s	ee instructions for more detail).	
VI. PHOTOGRAPHS Refer to attached p	notographs.		
All existing facilities must include photographs (aeriel or grousites of future storage, treatment or disposal areas (see instru	ictions for more detail).		
VII. FACILITY GEOGRAPHIC LOCATION This	information is provided	on the attached draw	rings and photos.
LATITUDE (degrees, minutes, & second	5/	LONGITUDE (degroes, m	inutes, & seconds)
VIII. FACILITY OWNER			
A. If the facility owner is also the facility operator as listed below. B. If the facility owner is not the facility operator as listed.			box to the left and skip to Section IX
1. NAME OF F	ACILITY'S LEGAL OWNER		2. PHONE NO. (area code & no.)
3. STREET OR P.O. BOX	4 CITY	OR TOWN 5. s	GT. 6. ZIP CODE
	T T T T T T T T T T T T T T T T T T T		
 		┸┯┖┸┯┸┸┸┸┸┸┸	╾┦ ├ ╼┸┸ ╾┸╼┼
IX. OWNER CERTIFICATION			——————————————————————————————————————
I certify under penalty of law that I have personally examined inquiry of those individuals immediately responsible for obtain there are significant penalties for submitting false information	ng the information, I believe that the .	submitted information is true, acc	documents, and that based on my curate, and complete. I am aware that
NAME (print or type)	SIGNATUALE	DA	TE SIGNED
John D. Wagoner, Manager U.S. Department of Energy	(/-/ 1/) / 1	1	5/7.5/95
Richland Operations Office	Gran W. Wags	m !) / 2 <i>5/95</i>
X. OPERATOR CERTIFICATION	// /		
I certify under penalty of law that I have personally examined inquiry of those individuals immediately responsible for obtain there are significant penalties for submitting false information	ng the information. I believe that the .	submitted information is true ac-	documents, and that based on my curate, and complete. I am aware that
NAME (print or type)	SIGNATURE	DA	TE SIGNED
		1	
SEE ATTACHMENT			

X. OPERATOR CERTIFICATION

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.


Owner/Sperator

John D. Wagoner, Manager U.S. Department of Energy Richland Operations Office 5(25(95

Co-operator

A. LaMar Trego, President Westinghouse Hanford Company 5/4/95 Date

T PLANT COMPLEX SITE PLAN



T Plant Complex O5/25/95, Page 27 of 40

T Plant Complex - Site Boundary - 46*45" 200 West Site Boundary T Plant MO-739 ∏ Complex MO-835 Hanford Site MO-892 Low Flash Point Storage #13 MO-371 Waste 90 Dock 2 Day Storage 221-TA 2) 2712-T 221-T First Floor 241-TX-154 **Diversion Box Enclosure** Cut Une to Sandfilter MO-289 Waste Container Storage Areas Sandfilter (Out of Service) 222-T 292-T 224-T 1 - 221-T Tunnel Storage 291-T - 221-T Canyon Control House Stack 291-T 214-T Storage Building 212 425 Feet 2706-T Building /5 - 2706-T Pad 119'37'09"


6 - 2706-T Yard

H9504027.1

130 Meters


65

T PLANT COMPLEX - 221-T SITE PLAN




T Plant Complex Rev. 4, 05/25/95, Page 29 of 40

T PLANT COMPLEX - 221-T CUTAWAY



T Plant Complex 05/25/95, Page 30 of 40

T Plant Complex - 2706-T Site Plan



H9504027.2

T Plant Complex Rev. 4, 05/25/95, Page 32 of 40


T PLANT COMPLEX AERIAL VIEW



221-T BUILDING

46°30'38" 119°30'40"

93030994-1220N (PHOTO TAKEN 1993)



T PLANT COMPLEX 221-T BUILDING




TYPICAL THIMBLE

46°30'38" 119°30'40"

93051132-3CN (PHOTO TAKEN 1993)

T PLANT COMPLEX 221-T BUILDING



TYPICAL THIMBLE INTERNAL VIEW

46°30'38" 119°30'40"

93051473-9CN (PHOTO TAKEN 1993)

T PLANT COMPLEX 221-T BUILDING



TYPICAL TROUGH

46°30'38" 119°30'40"

93060740-10CN (PHOTO TAKEN 1993)

T Plant Complex Rev. 4, 05/25/95, Page 36 of 40

T PLANT COMPLEX 221-T BUILDING



CANYON DECK

46°30'38" 119°30'40"

93051132-8CN (PHOTO TAKEN 1993)






AERIAL VIEW

46°30'38" 119°30'40"

93030994-257CN (PHOTO TAKEN 1993)

T PLANT COMPLEX 2706-T BUILDING




RAILROAD PIT

46°30'38" 119°30'40"

93040127-3CN (PHOTO TAKEN 1993)

T Plant Complex Rev. 4, 05/25/95, Page 39 of 40

T PLANT COMPLEX 2706-T BUILDING




AUTOMOTIVE PIT

46°30'38" 119°30'40"


93040127-2CN (PHOTO TAKEN 1993)







46°30'38" 119°30'40"



93040127-13CN (PHOTO TAKEN 1993)